

DST2007 Product Compliance Information

LTR4-512 Series Master Control Clock



Action Required

Automatic DST change:	Yes
Status:	Action Required
Serial numbers affected:	L-103073 or earlier
Action:	<p>The unit's firmware must be updated to a new version to support the new DST dates. This can be accomplished via an EPROM update, or installing a new front panel. Alternatively, a GPS receiver unit can be added-on for automatic synchronization to the US Atomic Clock bypassing the need for a firmware update.</p> <p>Factory update service and advanced replacement panel options are available. Please call (800) 241-4990 for more information.</p>